Work Ord September 02, 2												Page 1
Item ID: Revision ID: Item Name:	AN5C35A			Accept			Setup	Start Stop	1 10 411101 4			
Start Date: Required Date: Reference:	09/03/09 09/07/09 Return 2009	Start Qty: 2.00 Req'd Qty: 2.00 / RA109072			Cust Item I	ID:				•		
Approvals:	ovals: Process Plan: QC:		Date:	Tooling: SPC (Y/N):	D		Run	Start Stop				
Sequence ID/ Work Center II		Operation Description		Set Up/ Run Hours	Draw Number	Draw Rev.	Plan Code	Accept Qty	Rej Qty		Reject Number	Insp. Stamp
Draw Nbr	Revi	ision Nbr										,
		QC5- Inspect part comp	oleteness to step on W/O	0.00				24/16			*, ***	15:08:
QC Quality Control			a qty 2 M107551 V	0.00								1970
110 Packaging Packaging		Memo	tock Location: 340 307 tock using the ORIGINAL b	0.00 0.00	.04					169,	) 	1 _ 2/10
r acraging			o make stock adjustment**	oaten # s.	-09-04							

120

QC21- Final Inspection - Work Order Release

0.00

Quality Control

Memo

0.00

September 02, 2009 8:52:59 AM

Work Order ID: 51732

Parent Item:

AN5C35A

Parent Item Name:

Comments



Main Warehouse Return 2009

Main Warehouse ST

108409

111925 112431

Start Date: 09/03/09

Required Date: 09/07/09

Start Oty: 2.00

Required Qty: 2.00

Comments.								~	····· • • • • • • • • • • • • • • • • •	and an en following		
Component Item ID/ Item Name	Replacement Item ID	Mfg/ Purch	Bin Item	•	Last Location	Route Seq ID	Unit of Measure	Qty on Hand	Remaining Qty To Pick	Qty Issued	Date Issued	Status
AN3C41A		Purchased	No	,,,			Each	191.0000	16.0000		Cv 9/5	14
				Warehouse		Loc Oty		Loc Code				
	<u>Location</u> OFFSHORE		<u>Locatio</u>	<u>n</u>								
			3									
				FG			4					
				10	03324		4					

AN5C35A

Purchased

No

100 130.0000 2.0000 Each

Loc Oty Warehouse Loc Code Location Main Warehouse Return 2009 ×2 107551 Main Warehouse ST 129 107551 29 108084 50 108407 50

16

16

171 71